

Product Safety Voluntary Replacement Notice

High Visibility Vests

Recent quality testing carried out on Optipro WT-C001 and WCT-002 Vests supplied to the public between Sep and Dec 2011 have highlighted a performance issue relating to the reflective tape used on these products.

What is the Issue ?

The products are manufactured to European Standards EN471 and EN1150 which require a specific area of bright coloured day time visible material and a retro reflective tape which provides increased visibility at night time, however our quality testing has shown irregularities with the night time material. This means that it may be less bright than the standard asks for.

What do I need to do ?

Only vests that have an Optipro neck label without a batch label are affected.

If you have a vest with RSA branding and an Optipro Neck label which does not have a batch number tag you can return it Freepost to Optipro, PO Box 861, South City Delivery Office, Togher, FREEPOST FCK718, Cork with details of your return address and a free of charge replacement will be issued to you.(see images for guidance).

If you have any queries regarding this please call



FreePhone 1800 989822 where you can obtain further information about this exchange programme.